



# HEIDENHAIN




## NC Solutions

Description of NC program 2130

English (en)  
8/2017

## 1 Description of the NC program 2130\_en.h

NC program for milling a pocket in the shape of a P3G polygon as per DIN 32711



### Description

With this NC program, the control mills a P3G polygon pocket in accordance with DIN 32711. At program start, you define the tool and all the parameters required for machining.

Then the control starts the machining operation. After the conversion of the coordinates into the center of the polygon, the subprogram LBL1 is assigned in a Cycle 14. In this subprogram 1, the control calculates the contour of the polygon. The contour consists of individual points, for which the control calculates the X coordinate and the Y coordinate. The control then approaches the calculated point in a linear block. The control repeats this calculation and positioning process until the contour is closed. The control roughs out the calculated contour with Cycles 20 and 22.

After completion of the machining operation, the tool is retracted, the control resets all coordinate conversions, and the control ends the NC program.

Parameter	Name	Meaning
Q50	MILLING DEPTH	Depth of the pocket
Q51	PLUNGING DEPTH	Incremental depth at which the control feeds the tool along the tool axis.
Q52	SET UP CLEARANCE	Z-axis clearance between the tool and workpiece surface; the control approaches this clearance in rapid traverse.
Q53	FEED RATE FOR PLUNGING	Traversing speed at which the tool travels in the Z axis
Q54	FEED RATE FOR MILLING	Traversing speed of the tool during machining
Q30	ORBIFORM DIAMETER	Orbiform diameter of the polygon see "P3G polygon as per DIN 32711", page 3
Q31	ECCENTRIC SIZE (E)	Eccentric size of the polygon see "P3G polygon as per DIN 32711", page 3
Q36	CENTER OF THE POLYGON IN THE X AXIS	X coordinate of the center of the polygon
Q37	CENTER OF THE POLYGON IN THE Y AXIS	Y coordinate of the center of the polygon
Q38	ROTATION	Angle at which the coordinate system is rotated around the center of the polygon

**P3G polygon as per DIN 32711**

Geometric dimensions that you require to machine a pocket with the program 2130\_en.h

<b>Nominal size</b>	<b>Orbiform diameter (D1)<sup>1)</sup></b>	<b>Eccentric size (E)<sup>1)</sup></b>
14	14	0.44
16	16	0.5
18	18	0.56
20	20	0.63
22	22	0.7
25	25	0.8
28	28	0.9
30	30	1
32	32	1.12
36	36	1.25
40	40	1.4
45	45	1.6
50	50	1.8
55	55	2
60	60	2.25
65	65	2.45
70	70	2.8
75	75	3.15
80	80	3.4
85	85	3.55
90	90	4
95	95	4.25
100	100	4.5

<sup>1)</sup> Dimensions in mm

