



## New touch probe cycles

TNC 640

WEBINAR



# CONTENT

- 1. Overview and application possibilities**
- 2. New input parameters**
- 3. Programming**
- 4. Examples of use**




# 1 Overview and application possibilities



# Overview Cycles

- 1410 TOUCHING EDGE
- 1411 SENSING TWO CIRCUITS
- 1420 TOUCHING PLANE









# Application possibilities

## Cycles

- Determination of rotations
- Semi-automatic probing
- Monitoring of tolerances
- Alignment via basic rotation or table rotation
- Describing the 3D basic rotation





# 2 New input parameters



# New input parameters

## Axis position

### Absolutely

Q1100 = +45 ; 1ST POINT MAIN AXIS

### Semi-automatic mode

QS1100 = "?+45" ;1ST POINT MAIN AXIS

### Tolerances

QS1100 = "+45-1-0.5" ;1ST POINT MAIN AXIS

### Transfer of an actual position

QS1100 = "+45@45.1" ;1ST POINT MAIN AXIS

Program Run Full S... Programming

```

TNC:\Webinar_14xx\14xx.h
→3rd nominal position tool axis?
0 BEGIN PGM 14XX MM
1 BLK FORM 0.1 Z X-50 Y-50 Z-20
2 BLK FORM 0.2 X+50 Y+50 Z+0
3 TOOL CALL "TOUCH_PROBE" Z
4 TCH PROBE 1420 PROBING IN PLANE
    QS1100=?-40" ;1ST POINT REF AXIS
    QS1101=?-40" ;1ST POINT MINOR AXIS
    QS1102=?-2" ;1ST POINT TOOL AXIS
    QS1103=@40" ;2ND POINT REF AXIS
    QS1104=@40" ;2ND POINT MINOR AXIS
    QS1105=@-2" ;2ND POINT TOOL AXIS
    QS1106=+0.02" ;3RD POINT REF AXIS
    QS1107=40-0.05" ;3RD POINT MINOR AXIS
    QS1108=-3-0.09-0.02" ;3RD POINT TOOL AXIS
    Q372=-3" ;PROBING DIRECTION
    Q320=+0" ;SET-UP CLEARANCE
    Q260=+50" ;CLEARANCE HEIGHT
    Q1125=+2" ;CLEAR. HEIGHT MODE
    Q309=+0" ;ERROR REACTION
    Q1126=+2" ;ALIGN ROTARY AXIS
    Q1120=+0" ;TRANSER POSITION
    Q1121=+1" ;CONFIRM ROTATION
5 STOP
6 END PGM 14XX MM

```

BEGIN    END    MOVE WORD    MOVE WORD    INSERT    QS    ENTER NUMBER

Diagram illustrating the 3rd nominal position tool axis. The workpiece has three points: 1 (1st point main axis), 2 (2nd point minor axis), and 3 (3rd point tool axis). The Z-axis is vertical, the X-axis is horizontal, and the Y-axis is depth. The 3rd nominal position tool axis is indicated by a blue arrow pointing along the Z-axis.



# New input parameters

## Align rotary axes

### ■ STAY


Q1126 = 0

### ■ MOVE

Q1126 = 1

### ■ TURN

Q1126 = 2





# New input parameters

## Position for takeover

### ■ No takeover

Q1120 = 0

### ■ Acceptance of the 1st measuring point

Q1120 = 1

### ■ Acceptance of the 2nd measuring point

Q1120 = 2

### ■ Acceptance of the averaged measuring point

Q1120 = 3

Program Run Full S... Programming Programming

TNC:\Webinar\_14xx\14  
→ Transfer position?

```
0 BEGIN PGM 14XX MM
1 BLK FORM 0.1 Z X-
2 BLK FORM 0.2 X+5
3 TOOL CALL "TOUCH_
4 TCH PROBE 1420 PR
    QS1100=?-40" ;1
    QS1101=?-40" ;1
    QS1102=?-2" ;1
    QS1103=@40" ;2
    QS1104=@40" ;2
    QS1105=@-2" ;2
    QS1106="0+0.02"
    QS1107="40-0.05"
    QS1108="-3-0.09-
    Q372=-3 ;PROB
    Q320=+0 ;SET-I
    Q260=+50 ;CLEAR
    Q1125=+2 ;CLEAR
    Q309=+0 ;ERROR
    Q1126=+2 ;ALI
    Q1120=0 TRANS
    Q1121=+1 ;CON
5 STOP
6 END PGM 14XX MM
```

Q1120=0

\* .PR X Y Z

Q1120=

\* .PR X Y Z

TNC 640 HEIDENHAIN



# New input parameters

Accept rotation as

■ No takeover

Q1121 = 0

■ Set basic rotation

Q1121 = 1

■ Execute rotary table rotation

Q1122 = 2


Program Run Full S... Programming Programming

TNC : \Webinar\_14xx\1410


→CONFIRM ROTATION?

```
0 BEGIN PGM 1410 MM
1 BLK FORM 0.1 Z X-5
2 BLK FORM 0.2 X+50
3 TOOL CALL "TOUCH_P...
4 TCH PROBE 1410 PROB
    Q1100=-10 ;1ST
    Q1101=+10 ;1ST
    Q1102=-5 ;1ST
    Q1103=+10 ;2ND
    Q1104=+10 ;2ND
    Q1105=-5 ;2ND
    Q372=+2 ;PROBING
    Q320=+0 ;SET-UP
    Q260=+100 ;CLEAR
    Q1125=+2 ;CLEAR
    Q309=+0 ;ERROR
    Q1126=+0 ;ALIGN
    Q1120=+0 ;TRANS
    Q1121=0 CONFIRM
5 STOP
6 END PGM 1410 MM
```

Q1121=0 → 

Q1121=1 → 

Q1121=2 → 



TNC 640 HEIDENHAIN





# 3 Programming



# Programming

- Programming Target Coordinates
- Probing direction:  
X+/X- Y+/Y- Z+/Z-
- Active reference point is described
- Touch probe results are stored as of Q950







# 4 Examples of use



# Application example 1

## Surface Alignment

- Coordinates of the component are **known**
- Input of the nominal coordinates (important  
 $Z+0$ )
- Specifying the points define the coordinate system







# Application example 1

# Align edge

- Coordinates of the component are **known**
  - Input of the nominal coordinates (important)  
 $Y+0)$






## Application example 2

### Surface Alignment

- Coordinates of the component are **unknown**
- Input of the nominal coordinates (important  
 $Z+0$ )
- Specifying the points define the coordinate system







## Application example 2

### Align edge

- Coordinates of the component are **unknown**
- Input of the nominal coordinates (important  
 $Y+0$ )





# Application example 3

## Surface Alignment with three balls

- Nominal position of the balls known
- Measure actual position
- Calculate with cycle 1420:

Nominal position@actual position

- cycle calculates the rotations





## Contact me:

Phone +49 8669 31-3103

E-Mail [3103@heidenhain.de](mailto:3103@heidenhain.de)

# WEBINAR