

HEIDENHAIN




NC Solutions

Description of NC program 1110

English (en) 4/2017

1 Description of NC programs 1110_en.h and 11101_en.h

NC program for defining a point pattern as a circle and generating the holes with bore milling at the machining positions.



Description

With this NC program the control generates a point pattern in the form of a circle. At the calculated positions the control calls the NC program 11101_en.h. With this NC program the control machines holes with a bore-milling strategy.

1110_en.h NC program

In the first part of the NC program you define all parameters required for the calculation. The control then implements three calculations. You define the tool in the next program section, and in Cycle 12 you define the file path of the NC program run by the control at the calculated positions. The control calls a subprogram. The control executes all calculations and positioning movements in this subprogram. The control calculates the positions so that it approaches these positions in a peripheral path and executes machining. After the last machining step the control retracts the tool and terminates the program.

Circular hole pattern parameters

| Parameter | Name | Meaning |
|-----------|---|--|
| Q31 | CIRCULAR HOLE PATTERN RADIUS | Radius of the circular hole pattern generated by the control |
| Q32 | STARTING ANGLE | Polar angle related to the circular hole pattern center at which the control executes the first machining step |
| Q33 | CENTER OF CIRCULAR HOLE PATTERN IN THE X AXIS | X coordinate of the circular hole pattern center |
| Q34 | CENTER OF CIRCULAR HOLE PATTERN IN THE Y AXIS | Y coordinate of the circular hole pattern center |
| Q35 | STEPPING ANGLE | Incremental angle between two machining steps |
| Q36 | NUMBER OF OPERATIONS | Number of machining steps run by the control |

Hole parameters

| Parameter | Name | Meaning |
|-----------|-------------------------|---|
| Q40 | HOLE DIAMETER | Outside diameter of the holes |
| Q41 | DEPTH | Absolute depth of the holes |
| Q42 | NUMBER OF HELICAL PATHS | Number of 360° helical paths with each hole |
| Q43 | SAFETY CLEARANCE | Z clearance between the tool and workpiece surface approached by the control in rapid traverse before machining |
| Q44 | FEED RATE FOR MILLING | Traversing speed of the tool during machining |

11101_en.h NC program

The control executes all path contours for the bore milling sequence in this NC program. If you do not wish to change the drilling sequence you do not need to edit this program because all required parameters are defined in the main program.

Bore milling sequence

- 1 The control uses the pre-positioning coordinates for the circle center point
- 2 The control approaches the starting point of the helical path in the XY plane
- 3 The control approaches the starting point in the Z plane
- 4 The tool executes a helical path until the drilling depth is reached
- 5 At the bottom of the hole the control executes a 360° circular path to generate a face
- 6 The control positions the tool at the center of the hole
- 7 The tool retracts to safety clearance
- 8 Bore milling is complete and the control returns to the main program

