



# HEIDENHAIN



## **TNC 320 / TNC 620 / TNC 640**

Solutions  
Programming Station Exercises

**HIT Learning Package**  
**Milling – 3+2-Axis Machining**

English (en)  
8/2019

## Contents

<b>1</b>	<b>Fundamentals of tilted machining.....</b>	<b>4</b>
<b>2</b>	<b>Advanced topics of tilted machining.....</b>	<b>17</b>
<b>3</b>	<b>Related and further topics.....</b>	<b>49</b>

<b>1</b>	<b>Fundamentals of tilted machining.....</b>	<b>4</b>
1.1	Programming one spatial angle – 1277121.....	5
1.2	Programming one spatial angle – 1157579.....	12
<b>2</b>	<b>Advanced topics of tilted machining.....</b>	<b>17</b>
2.1	Programming one spatial angle – 1277117.....	18
2.2	Programming one spatial angle – 1267097.....	29
2.3	Programming more than one spatial angle – 1277110.....	36
2.4	Programming more than one spatial angle – 1277113.....	42
<b>3</b>	<b>Related and further topics.....</b>	<b>49</b>
3.1	Programming more than one transformation – 1277115.....	50
3.2	Programming more than one transformation – 1277120.....	57
3.3	Programming more than one transformation – 1277112.....	65


# 1

**Fundamentals of  
tilted machining**

### 1.1 Programming one spatial angle – 1277121

1:1

Text:			ID number			
			Change No.	C000941-05		
			Phase:	Nicht-Serie		
			Werkstoff: Material:	3.1645		
			●blanke Flächen/Blank surfaces			
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing				
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715		Allgemeintoleranzen ISO 2768-mH General tolerances ISO 2768-mH		Tolerierung nach ISO 8015 Tolerances as per ISO 8015		
		$\leq 6\text{mm}: \pm 0,2$ $\leq 6\text{mm}: \pm 0,2$		Oberflächen nach ISO 1302 Surfaces as per ISO 1302		
Oberflächenbehandlung: Surface treatment:						
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )						
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany		Created	Responsible	Released	Version   Revision   Sheet   Page	
		M-TS			<b>D1277121-00-A-01</b>	1 of 1
		11.01.2019				



Text:		ID number														
		Change No. C000941-05														
		Phase: Nicht-Serie														
		Werkstoff: 3.1645														
		Material:														
<table border="1"> <tr> <td></td> <td>Original drawing</td> <td colspan="2" rowspan="2" style="text-align: center;"><b>Platte</b></td> </tr> <tr> <td></td> <td>Scale    Format</td> </tr> <tr> <td>RoHS</td> <td>1:2    A4</td> <td colspan="2" style="text-align: center;"><b>plate</b></td> </tr> <tr> <td colspan="2">Maße in mm / Dimensions in mm</td> <td colspan="2" style="text-align: center;">Einzelteilzeichnung / Component Drawing</td> </tr> </table>			Original drawing	<b>Platte</b>			Scale    Format	RoHS	1:2    A4	<b>plate</b>		Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing		●blanke Flächen/Blank surfaces
	Original drawing	<b>Platte</b>														
	Scale    Format															
RoHS	1:2    A4	<b>plate</b>														
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing														
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715 		Allgmeintoleranzen ISO 2768-mH    ≤6mm: ±0,2 General tolerances ISO 2768-mH    ≤6mm: ±0,2	Tolerierung nach ISO 8015 Tolerances as per ISO 8015  Oberflächenbehandlung: Surface treatment:													
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )																
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany		Created	Responsible													
		M-TS														
		Released	Version													
			Revision													
			Sheet													
			Page													
		<b>D1277121-00-A-02</b>														
		Document number														
		1 of 1														



**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Safe tilting position
- ▶ Shift datum to tilting edge
- ▶ Tilt the working plane
- ▶ Mill the inclined surface (10°)
- ▶ Mill the circular pocket
- ▶ Tool call
- ▶ Safe tilting position
- ▶ Shift datum to tilting edge
- ▶ Tilt the working plane
- ▶ Mill the chamfer on the circular pocket
- ▶ Reset tilting
- ▶ Reset datum shift

**Program parameters**

<b>Face milling (roughing)</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Milling plan	2, climb milling			
Milling direction	1, parallel to X axis			
Feed rate for pre-positioning	Maximum feed rate			
<b>Circular pocket milling (roughing)</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Pre-position		+30	+50	-
Machining direction	Climb milling			
Plunging motion	Helical			
<b>Milling of chamfer on circular pocket (finishing)</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Pre-position		+30	+50	-
Machining direction	Climb milling			
Plunging motion	Helical			
<b>General parameters</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	<b>Ø</b>	<b>T</b>	<b>S</b>	<b>F<sub>1</sub></b>	<b>DZ</b>	<b>IZ</b>	<b>DL</b>	<b>DR</b>
	20	10	5000	1000	-10	5	-	-
	10	172	4300	730	-10	5	-2.5	-2.5

Ø) Diameter

T) Tool number

S) Speed

F<sub>1</sub>) Machining feed rate

DZ) Max. machining depth

IZ) Infeed

DL) Tool oversize: delta value for length

DR) Tool oversize: delta value for radius



## Solution


0	BEGIN PGM 1277121 MM
1	BLK FORM 0.1 Z X+0 Y+0 Z-40
2	BLK FORM 0.2 X+100 Y+100 Z+0
3	TOOL CALL 10 Z S5000 F1000
4	L Z+300 R0 FMAX M3 M91
5	L X+300 Y-300 R0 FMAX M91
6	CYCL DEF 7.0 DATUM SHIFT
7	CYCL DEF 7.1 X+30
8	PLANE SPATIAL SPA+0 SPB+10 SPC+0 TURN FMAX
9	CYCL DEF 233 FACE MILLING ~
	Q215=+1 ;MACHINING OPERATION ~
	Q389=+2 ;MILLING STRATEGY ~
	Q350=+1 ;MILLING DIRECTION ~
	Q218=-75 ;FIRST SIDE LENGTH ~
	Q219=+100 ;2ND SIDE LENGTH ~
	Q227=+12.5 ;STARTNG PNT 3RD AXIS ~
	Q386=+0 ;END POINT 3RD AXIS ~
	Q369=+0 ;ALLOWANCE FOR FLOOR ~
	Q202=+5 ;MAX. PLUNGING DEPTH ~
	Q370=+1 ;TOOL PATH OVERLAP ~
	Q207= AUTO ;FEED RATE MILLING ~
	Q385=+500 ;FINISHING FEED RATE ~
	Q253= MAX ;F PRE-POSITIONING ~
	Q357=+2 ;CLEARANCE TO SIDE ~
	Q200=+2 ;SET-UP CLEARANCE ~
	Q204=+50 ;2ND SET-UP CLEARANCE ~
	Q347=+0 ;1ST LIMIT ~
	Q348=+0 ;2ND LIMIT ~
	Q349=+0 ;3RD LIMIT ~
	Q220=+0 ;CORNER RADIUS ~
	Q368=+0 ;ALLOWANCE FOR SIDE ~
	Q338=+0 ;INFEEED FOR FINISHING ~
10	L X+75 Y+0 Z+50 R0 FMAX M99
11	CYCL DEF 252 CIRCULAR POCKET ~
	Q215=+1 ;MACHINING OPERATION ~
	Q223=+50 ;CIRCLE DIAMETER ~
	Q368=+0 ;ALLOWANCE FOR SIDE ~
	Q207= AUTO ;FEED RATE MILLING ~
	Q351=+1 ;CLIMB OR UP-CUT ~
	Q201=-10 ;DEPTH ~
	Q202=+5 ;PLUNGING DEPTH ~
	Q369=+0 ;ALLOWANCE FOR FLOOR ~

Q206= AUTO	;FEED RATE FOR PLNGNG ~
Q338=+0	;INFEED FOR FINISHING ~
Q200=+2	;SET-UP CLEARANCE ~
Q203=+0	;SURFACE COORDINATE ~
Q204=+50	;2ND SET-UP CLEARANCE ~
Q370=+1	;TOOL PATH OVERLAP ~
Q366=+1	;PLUNGE ~
Q385=+500	;FINISHING FEED RATE ~
Q439=+0	;FEED RATE REFERENCE
12 L X+30 Y+50 Z+50 R0 FMAX M99	
13 PLANE RESET TURN FMAX	
14 CYCL DEF 7.0 DATUM SHIFT	
15 CYCL DEF 7.1 X+0	
16 CYCL DEF 7.2 Y+0	
17 CYCL DEF 7.3 Z+0	
18 TOOL CALL 172 Z S4300 F7300 DL-2.5 DR-2.5	
19 L Z+300 R0 FMAX M3 M91	
20 L X+300 Y-300 R0 FMAX M91	
21 CYCL DEF 7.0 DATUM SHIFT	
22 CYCL DEF 7.1 X+30	
23 PLANE SPATIAL SPA+0 SPB+10 SPC+0 TURN FMAX	
24 CYCL DEF 252 CIRCULAR POCKET ~	
Q215=+2	;MACHINING OPERATION ~
Q223=+50	;CIRCLE DIAMETER ~
Q368=+0.2	;ALLOWANCE FOR SIDE ~
Q207= AUTO	;FEED RATE MILLING ~
Q351=+1	;CLIMB OR UP-CUT ~
Q201=-1.2	;DEPTH ~
Q202=+5	;PLUNGING DEPTH ~
Q369=+0	;ALLOWANCE FOR FLOOR ~
Q206= AUTO	;FEED RATE FOR PLNGNG ~
Q338=+0	;INFEED FOR FINISHING ~
Q200=+2	;SET-UP CLEARANCE ~
Q203=+0	;SURFACE COORDINATE ~
Q204=+50	;2ND SET-UP CLEARANCE ~
Q370=+1	;TOOL PATH OVERLAP ~
Q366=+1	;PLUNGE ~
Q385=+500	;FINISHING FEED RATE ~
Q439=+0	;FEED RATE REFERENCE
25 L X+30 Y+50 Z+50 R0 FMAX M99	
26 PLANE RESET TURN FMAX	
27 CYCL DEF 7.0 DATUM SHIFT	
28 CYCL DEF 7.1 X+0	

29 CYCL DEF 7.2 Y+0	
30 CYCL DEF 7.3 Z+0	
31 M30	
32 END PGM 1277121 MM	

## 1.2 Programming one spatial angle – 1157579

Text:		ID number										
		Change No.	C000941-05									
		Phase:	Nicht-Serie									
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;"> </td> <td style="text-align: center;">Original drawing</td> <td></td> </tr> <tr> <td style="text-align: center;">RoHS</td> <td style="text-align: center;">Scale</td> <td style="text-align: center;">Format</td> </tr> <tr> <td style="text-align: center;">1:1</td> <td style="text-align: center;">A4</td> <td></td> </tr> </table>		Original drawing		RoHS	Scale	Format	1:1	A4		<b>Platte</b> <b>Plate</b>		Werkstoff: Material:
	Original drawing											
RoHS	Scale	Format										
1:1	A4											
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing										
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715 		Allgemeintoleranzen ISO 2768-mH General tolerances ISO 2768-mH $\leq 6\text{mm}: \pm 0,2$ $\leq 6\text{mm}: \pm 0,2$	Tolerierung nach ISO 8015 Tolerances as per ISO 8015 Oberflächenbehandlung: Surface treatment:	●blanke Flächen/Blank surfaces Oberflächen nach ISO 1302 Surfaces as per ISO 1302								
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )												
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany		Created	Responsible	Released								
		M-TS										
		<b>D1157579-00-A-01</b>		Version   Revision   Sheet   Page 1   of   1								
		Document number										



Text:		ID number																	
Change No. C000941-05		Phase: Nicht-Serie																	
Werkstoff: Material:		●blanke Flächen/Blank surfaces																	
<table border="1"> <tr> <td></td> <td>Original drawing</td> <td colspan="2">Platte</td> </tr> <tr> <td>Scale</td> <td>Format</td> <td colspan="2">Plate</td> </tr> <tr> <td>1:1</td> <td>A4</td> <td colspan="2">Dokumentenart / Document type</td> </tr> </table>		Original drawing	Platte		Scale	Format	Plate		1:1	A4	Dokumentenart / Document type		Maße in mm / Dimensions in mm						
	Original drawing	Platte																	
Scale	Format	Plate																	
1:1	A4	Dokumentenart / Document type																	
<table border="1"> <tr> <td>Werkstückkanten nach ISO 13715</td> <td>Allgemeintoleranzen ISO 2768-mH</td> <td>≤6mm: ±0,2</td> <td>Tolerierung nach ISO 8015</td> </tr> <tr> <td>Workpiece edges ISO 13715</td> <td>General tolerances ISO 2768-mH</td> <td>≤6mm: ±0,2</td> <td>Tolerances as per ISO 8015</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Oberflächenbehandlung:</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Surface treatment:</td> </tr> </table>	Werkstückkanten nach ISO 13715	Allgemeintoleranzen ISO 2768-mH	≤6mm: ±0,2	Tolerierung nach ISO 8015	Workpiece edges ISO 13715	General tolerances ISO 2768-mH	≤6mm: ±0,2	Tolerances as per ISO 8015				Oberflächenbehandlung:				Surface treatment:	Oberflächen nach ISO 1302 Surfaces as per ISO 1302		
Werkstückkanten nach ISO 13715	Allgemeintoleranzen ISO 2768-mH	≤6mm: ±0,2	Tolerierung nach ISO 8015																
Workpiece edges ISO 13715	General tolerances ISO 2768-mH	≤6mm: ±0,2	Tolerances as per ISO 8015																
			Oberflächenbehandlung:																
			Surface treatment:																
<p>The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )</p>																			
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created	Responsible	Released																
	M-TS																		
09.11.2015																			
Version			Revision																
Sheet			Page																
D1157579-00 - A-02			1 of 1																
Document number																			

**Working plan**


- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Safe tilting position
- ▶ Shift datum to tilting edge
- ▶ Tilt the working plane
- ▶ Mill the front slot
- ▶ Reset transformations mathematically
- ▶ Shift datum to tilting edge
- ▶ Tilt the working plane
- ▶ Mill the left-hand slot
- ▶ Reset tilting
- ▶ Reset datum shift

**Program parameters**

Slot milling (roughing)	Parameters	X	Y	Z
Machining direction	Climb milling			
Plunging motion	Reciprocating			

General parameters	Parameters	X	Y	Z
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	Ø	T	S	F <sub>1</sub>	DZ	IZ
	8	4	12000	950	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

## Solution

0 BEGIN PGM 1157579 MM
1 BLK FORM 0.1 Z X+0 Y+0 Z-80
2 BLK FORM 0.2 X+60 Y+60 Z+0
3 TOOL CALL 4 Z S12000 F950
4 L Z+300 R0 FMAX M3 M91
5 L X+300 Y-300 R0 FMAX M91
6 CYCL DEF 7.0 DATUM SHIFT
7 CYCL DEF 7.2 X+30
8 CYCL DEF 7.3 Z-10
9 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX
10 CYCL DEF 253 SLOT MILLING ~
Q215=+1           ;MACHINING OPERATION ~
Q218=+45        ;SLOT LENGTH ~
Q219=+10        ;SLOT WIDTH ~
Q368=+0         ;ALLOWANCE FOR SIDE ~
Q374=+0         ;ANGLE OF ROTATION ~
Q367=+0         ;SLOT POSITION ~
Q207= AUTO      ;FEED RATE MILLING ~
Q351=+1         ;CLIMB OR UP-CUT ~
Q201=-10        ;DEPTH ~
Q202=+5         ;PLUNGING DEPTH ~
Q369=+0         ;ALLOWANCE FOR FLOOR ~
Q206= AUTO      ;FEED RATE FOR PLNGNG ~
Q338=+0         ;INFEED FOR FINISHING ~
Q200=+2         ;SET-UP CLEARANCE ~
Q203=+0         ;SURFACE COORDINATE ~
Q204=+50        ;2ND SET-UP CLEARANCE ~
Q366=+2         ;PLUNGE ~
Q385=+500       ;FINISHING FEED RATE ~
Q439=+3         ;FEED RATE REFERENCE
11 L X+0 Y+0 Z+50 R0 FMAX M99
12 PLANE RESET TURN FMAX
13 CYCL DEF 7.0 DATUM SHIFT
14 CYCL DEF 7.1 X+0
15 CYCL DEF 7.2 Y+0
16 CYCL DEF 7.3 Z+0
17 CYCL DEF 7.0 DATUM SHIFT
18 CYCL DEF 7.1 Y+30
19 CYCL DEF 7.3 Z-10
20 PLANE SPATIAL SPA+0 SPB-90 SPC+0 TURN FMAX
21 CYCL DEF 253 SLOT MILLING ~
Q215=+1           ;MACHINING OPERATION ~


Q218=+45	;SLOT LENGTH ~	
Q219=+10	;SLOT WIDTH ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q374=+90	;ANGLE OF ROTATION ~	
Q367=+0	;SLOT POSITION ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q351=+1	;CLIMB OR UP-CUT ~	
Q201=-10	;DEPTH ~	
Q202=+5	;PLUNGING DEPTH ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q338=+0	;INFEEED FOR FINISHING ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q366=+2	;PLUNGE ~	
Q385=+500	;FINISHING FEED RATE ~	
Q439=+3	;FEED RATE REFERENCE	
22 L X+0 Y+0 Z+50 R0 FMAX M99		
23 PLANE RESET TURN FMAX		
24 CYCL DEF 7.0 DATUM SHIFT		
25 CYCL DEF 7.1 X+0		
26 CYCL DEF 7.3 Y+0		
27 CYCL DEF 7.3 Z+0		
28 M 30		SAFE
29 END PGM 1157579 MM		





# 2


**Advanced topics of  
tilted machining**

## 2.1 Programming one spatial angle – 1277117











Text:		ID number							
Change No. C000941-05		Phase: Nicht-Serie							
Werkstoff: 3.1645		Material:							
<table border="1"> <tr> <th>Original drawing</th> <th>Scale</th> <th>Format</th> </tr> <tr> <td></td> <td>1:1</td> <td>A4</td> </tr> </table>		Original drawing	Scale	Format		1:1	A4	<p><b>Klotz</b></p> <p><b>block</b></p>	
Original drawing	Scale	Format							
	1:1	A4							
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing							
<p>Werkstückkanten nach ISO 13715</p> <p>Workpiece edges ISO 13715</p> <p><math>\swarrow</math> -0.3    <math>\searrow</math> +0.3</p>		<p>Allgemeintoleranzen ISO 2768-mH <math>\leq</math> 6mm: <math>\pm</math>0,2</p> <p>General tolerances ISO 2768-mH <math>\leq</math> 6mm: <math>\pm</math>0,2</p>							
Tolerierung nach ISO 8015		Tolerances as per ISO 8015							
Oberflächenbehandlung:		Surface treatment:							
●blanke Flächen/Blank surfaces		Oberflächen nach ISO 1302							
Surfaces as per ISO 1302									
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )									
<p><b>HEIDENHAIN</b></p> <p>DR. JOHANNES HEIDENHAIN GmbH</p> <p>83301 Traunreut, Germany</p>	Created	Responsible	Released						
	M-TS								
	11.01.2019								
Version		Revision	Sheet						
D1277117-00-A-02			Page						
Document number			3 of 5						



Text:		ID number							
		Change No. C000941-05							
		Phase: Nicht-Serie							
<table border="1"> <tr> <td></td> <td>Original drawing</td> <td colspan="2" rowspan="2" style="text-align: center; vertical-align: middle;"><b>Klotz</b> <b>block</b></td> </tr> <tr> <td>RoHS</td> <td>Scale: 1:1</td> <td>Format: A4</td> </tr> </table>			Original drawing	<b>Klotz</b> <b>block</b>		RoHS	Scale: 1:1	Format: A4	Werkstoff: 3.1645
	Original drawing	<b>Klotz</b> <b>block</b>							
RoHS	Scale: 1:1			Format: A4					
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing							
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715 		Allgemeintoleranzen ISO 2768-mH ≤6mm: ±0,2 General tolerances ISO 2768-mH ≤6mm: ±0,2	Tolerierung nach ISO 8015 Tolerances as per ISO 8015 Oberflächenbehandlung: Surface treatment:						
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )		●blanke Flächen/Blank surfaces Oberflächen nach ISO 1302 Surfaces as per ISO 1302							
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created	Responsible	Released						
	M-TS								
11.01.2019	<b>D1277117-00-A-02</b>		Version   Revision   Sheet   Page						
Document number			4 of 5						




**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill the inclined surfaces
- ▶ Mill the circle (Ø 24)
- ▶ Mill the circle (Ø 35)
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

<b>Face milling (roughing)</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Milling plan	2, climb milling			
Milling direction	2, parallel to Y axis			
Feed rate for pre-positioning	Maximum feed rate			
<b>Bore milling</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Machining direction	Climb milling			
Plunging depth	1			
<b>General parameters</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	<b>Ø</b>	<b>T</b>	<b>S</b>	<b>F<sub>1</sub></b>	<b>DZ</b>	<b>IZ</b>
	20	10	5000	1000	-81	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed



## Solution


0 BEGIN PGM 1277117 MM	
1 BLK FORM 0.1 Z X-32.5 Y+0 Z-65	
2 BLK FORM 0.2 X+32.5 Y+80 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 81	PLANE_1
6 CALL LBL 51	MACHINING_1
7 CALL LBL 98	RESET_COORD. TRANS.
8 CALL LBL 82	PLANE_2
9 CALL LBL 52	MACHINING_2
10 CALL LBL 98	RESET_COORD. TRANS.
11 CALL LBL 83	PLANE_3
12 CALL LBL 51	MACHINING_1
13 CALL LBL 98	RESET_COORD. TRANS.
14 CALL LBL 84	PLANE_4
15 CALL LBL 52	MACHINING_2
16 CALL LBL 98	RESET_COORD. TRANS.
17 CALL LBL 85	PLANE_6
18 CALL LBL 53	MACHINING_3
19 CALL LBL 98	RESET_COORD. TRANS.
20 CALL LBL 85	PLANE_6
21 CALL LBL 54	MACHINING_4
22 CALL LBL 99	RESET
23 M30	
24 LBL 51	MACHINING_1
25 CYCL DEF 233 FACE MILLING ~	
Q215=+1           ;MACHINING OPERATION ~	
Q389=+2           ;MILLING STRATEGY ~	
Q350=+2           ;MILLING DIRECTION ~	
Q218=+27.5       ;FIRST SIDE LENGTH ~	
Q219=+80         ;2ND SIDE LENGTH ~	
Q227=+12         ;STARTNG PNT 3RD AXIS ~	
Q386=+0           ;END POINT 3RD AXIS ~	
Q369=+0           ;ALLOWANCE FOR FLOOR ~	
Q202=+5           ;MAX. PLUNGING DEPTH ~	
Q370=+1           ;TOOL PATH OVERLAP ~	
Q207= AUTO        ;FEED RATE MILLING ~	
Q385=+500         ;FINISHING FEED RATE ~	
Q253= MAX         ;F PRE-POSITIONING ~	
Q357=+2           ;CLEARANCE TO SIDE ~	
Q200=+2           ;SET-UP CLEARANCE ~	
Q204=+50         ;2ND SET-UP CLEARANCE ~	


Q347=+0	;1ST LIMIT ~	
Q348=+0	;2ND LIMIT ~	
Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
26 L X+0 Y+0 Z+50 R0 FMAX M99		
27 LBL 0		
28 LBL 52		MACHINING_2
29 CYCL DEF 233 FACE MILLING ~		
Q215=+1	;MACHINING OPERATION ~	
Q389=+2	;MILLING STRATEGY ~	
Q350=+2	;MILLING DIRECTION ~	
Q218=+21	;FIRST SIDE LENGTH ~	
Q219=+80	;2ND SIDE LENGTH ~	
Q227=+5.5	;STARTNG PNT 3RD AXIS ~	
Q386=+0	;END POINT 3RD AXIS ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q202=+5	;MAX. PLUNGING DEPTH ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q385=+500	;FINISHING FEED RATE ~	
Q253= MAX	;F PRE-POSITIONING ~	
Q357=+2	;CLEARANCE TO SIDE ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q347=+0	;1ST LIMIT ~	
Q348=+0	;2ND LIMIT ~	
Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
30 L X+0 Y+0 Z+50 R0 FMAX M99		
31 LBL 0		
32 LBL 53		MACHINING_3
33 CYCL DEF 208 BORE MILLING ~		
Q200=+2	;SET-UP CLEARANCE ~	
Q201=-81	;DEPTH ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q334=+1	;PLUNGING DEPTH ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q335=+24	;NOMINAL DIAMETER ~	

Q342=+0	;ROUGHING DIAMETER ~	
Q351=+1	;CLIMB OR UP-CUT	
34 L X+0 Y+0 Z+50 R0 FMAX M99		
35 LBL 0		
36 LBL 54		MACHINING_4
37 CYCL DEF 208 BORE MILLING ~		
Q200=+2	;SET-UP CLEARANCE ~	
Q201=-20	;DEPTH ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q334=+1	;PLUNGING DEPTH ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q335=+35	;NOMINAL DIAMETER ~	
Q342=+24	;ROUGHING DIAMETER ~	
Q351=+1	;CLIMB OR UP-CUT	
38 L X+0 Y+0 Z+50 R0 FMAX M99		
39 LBL 0		
40 LBL 81		PLANE_1
41 CALL LBL 100		SAFE
42 CYCL DEF 7.0 DATUM SHIFT		
43 CYCL DEF 7.1 X+9		
44 PLANE SPATIAL SPA+0 SPB+30 SPC+0 TURN FMAX		
45 LBL 0		
46 LBL 82		PLANE_2
47 CALL LBL 100		SAFE
48 CYCL DEF 7.0 DATUM SHIFT		
49 CYCL DEF 7.1 X+32.5		
50 CYCL DEF 7.3 Z-29		
51 PLANE SPATIAL SPA+0 SPB+70 SPC+0 TURN FMAX		
52 LBL 0		
53 LBL 83		PLANE_3
54 CALL LBL 100		SAFE
55 CYCL DEF 7.0 DATUM SHIFT		
56 CYCL DEF 7.1 X-9		
57 CYCL DEF 7.2 Y+80		
58 PLANE SPATIAL SPA+0 SPB+30 SPC+180 TURN FMAX		
59 LBL 0		
60 LBL 84		PLANE_4
61 CALL LBL 100		SAFE
62 CYCL DEF 7.0 DATUM SHIFT		
63 CYCL DEF 7.1 X-32.5		
64 CYCL DEF 7.2 Y+80		
65 CYCL DEF 7.3 Z-29		

66 PLANE SPATIAL SPA+0 SPB+70 SPC+180 TURN FMAX	
67 LBL 0	
68 LBL 85	PLANE_5
69 CALL LBL 100	SAFE
70 CYCL DEF 7.0 DATUM SHIFT	
71 CYCL DEF 7.3 Z-27	
72 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX	
73 LBL 0	
74 LBL 98	RESET_COORD. TRANS.
75 PLANE RESET STAY	
76 CYCL DEF 7.0 DATUM SHIFT	
77 CYCL DEF 7.1 X+0	
78 CYCL DEF 7.2 Y+0	
79 CYCL DEF 7.3 Z+0	
80 LBL 0	
81 LBL 99	RESET
82 CALL LBL 100	SAFE
83 PLANE RESET TURN FMAX	
84 CYCL DEF 7.0 DATUM SHIFT	
85 CYCL DEF 7.1 X+0	
86 CYCL DEF 7.2 Y+0	
87 CYCL DEF 7.3 Z+0	
88 LBL 0	
89 LBL 100	SAFE
90 L Z+300 R0 FMAX M3 M91	
91 L X+300 Y-300 R0 FMAX M91	
92 LBL 0	
93 END PGM 1277117 MM	

## 2.2 Programming one spatial angle – 1267097





Text:		ID number	
Change No.	C000941-05	Change No.	C000941-05
Phase:	Nicht-Serie	Phase:	Nicht-Serie
Werkstoff:		Werkstoff:	
Material:		Material:	
Klotz		Blanker Flächen/Blank surfaces	
Block		Oberflächen nach ISO 1302	
Einzelteilzeichnung / Component Drawing		Surfaces as per ISO 1302	
Maße in mm / Dimensions in mm	Werkstücktoleranzen ISO 2768-mH	±0,2	
Scale	General tolerances ISO 2768-mH	±0,2	
Original drawing	Formate	±0,3	
Scale	Format		
1:1	A3		
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. (ISO 16016)			
HEIDENHAIN		Version/Revision/Sheet	
DR. JOHANNES HEIDENHAIN GmbH		D1267097-00-A-02	
83301 Trautent, Germany		Document number	
Created	Released	Version	Revision/Sheet
M-TS			1
17.09.2018			of
			1

**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill the left-hand inclined surface (45°)
- ▶ Mill the right-hand inclined surface (45°)
- ▶ Tool call
- ▶ Mill the circular pocket
- ▶ Mill rectangular pocket
- ▶ Slot milling
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**



Face milling (roughing)	Parameters	X	Y	Z
Milling plan	2, climb milling			
Milling direction	2, parallel to Y axis			
Feed rate for pre-positioning	Maximum feed rate			

Milling of circular pocket and rectangular pocket (roughing)	Parameters	X	Y	Z
Machining direction	Climb milling			
Plunging motion	Helical			

Slot milling (roughing)	Parameters	X	Y	Z
Machining direction	Climb milling			
Plunging motion	Reciprocating			

General parameters	Parameters	X	Y	Z
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	∅	T	S	F <sub>1</sub>	DZ	IZ
	20	10	5000	1000	-5	5
	8	4	12000	950	-10	5

- ∅) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

## Solution

0 BEGIN PGM 1267097 MM	
1 BLK FORM 0.1 Z X+0 Y+0 Z-80	
2 BLK FORM 0.2 X+60 Y+60 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 81	PLANE_1
6 CALL LBL 51	MACHINING_1
7 CALL LBL 98	RESET
8 CALL LBL 82	PLANE_2
9 CALL LBL 51	MACHINING_1
10 CALL LBL 99	RESET
11 TOOL CALL 4 Z S12000 F950	
12 CALL LBL 99	RESET
13 CALL LBL 81	PLANE_1
14 CALL LBL 52	MACHINING_2
15 CALL LBL 53	MACHINING_3
16 CALL LBL 98	RESET
17 CALL LBL 82	PLANE_2
18 CALL LBL 54	MACHINING_4
19 CALL LBL 99	RESET
20 M30	
21 LBL 51	MACHINING_1
22 CYCL DEF 233 FACE MILLING ~	
Q215=+1           ;MACHINING OPERATION ~	
Q389=+2           ;MILLING STRATEGY ~	
Q350=+2           ;MILLING DIRECTION ~	
Q218=+40          ;FIRST SIDE LENGTH ~	
Q219=+60          ;2ND SIDE LENGTH ~	
Q227=+25          ;STARTNG PNT 3RD AXIS ~	
Q386=+0           ;END POINT 3RD AXIS ~	
Q369=+0           ;ALLOWANCE FOR FLOOR ~	
Q202=+5           ;MAX. PLUNGING DEPTH ~	
Q370=+1           ;TOOL PATH OVERLAP ~	
Q207= AUTO        ;FEED RATE MILLING ~	
Q385=+500         ;FINISHING FEED RATE ~	
Q253= MAX         ;F PRE-POSITIONING ~	
Q357=+2           ;CLEARANCE TO SIDE ~	
Q200=+2           ;SET-UP CLEARANCE ~	
Q204=+50          ;2ND SET-UP CLEARANCE ~	
Q347=+0           ;1ST LIMIT ~	
Q348=+0           ;2ND LIMIT ~	
Q349=+0           ;3RD LIMIT ~	



Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
23 L X-40 Y+0 Z+50 R0 FMAX M99		
24 LBL 0		
25 LBL 52		MACHINING_2
26 CYCL DEF 252 CIRCULAR POCKET ~		
Q215=+1	;MACHINING OPERATION ~	
Q223=+20	;CIRCLE DIAMETER ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q351=+1	;CLIMB OR UP-CUT ~	
Q201=-10	;DEPTH ~	
Q202=+5	;PLUNGING DEPTH ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q338=+0	;INFEEED FOR FINISHING ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q366=+1	;PLUNGE ~	
Q385=+500	;FINISHING FEED RATE ~	
Q439=+0	;FEED RATE REFERENCE	
27 L X-17.5 Y+30 Z+50 R0 FMAX M99		
28 LBL 0		
29 LBL 53		MACHINING_3
30 CYCL DEF 251 RECTANGULAR POCKET ~		
Q215=+1	;MACHINING OPERATION ~	
Q218=+25	;FIRST SIDE LENGTH ~	
Q219=+40	;2ND SIDE LENGTH ~	
Q220=+5	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q224=+0	;ANGLE OF ROTATION ~	
Q367=+0	;POCKET POSITION ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q351=+1	;CLIMB OR UP-CUT ~	
Q201=-5	;DEPTH ~	
Q202=+5	;PLUNGING DEPTH ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q206= AUTO	;FEED RATE FOR PLNGNG . ~	
Q338=+0	;INFEEED FOR FINISHING ~	
Q200=+2	;SET-UP CLEARANCE ~	

Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q366=+1	;PLUNGE ~	
Q385=+500	;FINISHING FEED RATE	
31 L X-17.5 Y+30 Z+50 R0 FMAX M99		
32 LBL 0		
33 LBL 54		MACHINING_4
34 CYCL DEF 253 SLOT MILLING ~		
Q215=+1	;MACHINING OPERATION ~	
Q218=+40	;SLOT LENGTH ~	
Q219=+12	;SLOT WIDTH ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q374=+120	;ANGLE OF ROTATION ~	
Q367=+0	;SLOT POSITION ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q351=+1	;CLIMB OR UP-CUT ~	
Q201=-10	;DEPTH ~	
Q202=+8	;PLUNGING DEPTH ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q338=+0	;INFEED FOR FINISHING ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q366=+2	;PLUNGE ~	
Q385=+500	;FINISHING FEED RATE ~	
Q439=+3	;FEED RATE REFERENCE	
35 L X-17.5 Y+30 Z+50 R0 FMAX M99		
36 LBL 0		
37 LBL 81		PLANE_1
38 CALL LBL 100		SAFE
39 CYCL DEF 7.0 DATUM SHIFT		
40 CYCL DEF 7.1 X+25		
41 PLANE SPATIAL SPA+0 SPB-45 SPC+0 TURN FMAX		
42 LBL 0		
43 LBL 82		PLANE_2
44 CALL LBL 100		SAFE
45 CYCL DEF 7.0 DATUM SHIFT		
46 CYCL DEF 7.1 X+60		
47 CYCL DEF 7.3 Z-25		
48 PLANE SPATIAL SPA+0 SPB+45 SPC+0 TURN FMAX		
49 LBL 0		


50 LBL 98	RESET_COORD. TRANS.
51 PLANE RESET STAY	
52 CYCL DEF 7.0 DATUM SHIFT	
53 CYCL DEF 7.1 X+0	
54 CYCL DEF 7.2 Y+0	
55 CYCL DEF 7.3 Z+0	
56 LBL 0	
57 LBL 99	RESET
58 CALL LBL 100	SAFE
59 PLANE RESET TURN FMAX	
60 CYCL DEF 7.0 DATUM SHIFT	
61 CYCL DEF 7.1 X+0	
62 CYCL DEF 7.2 Y+0	
63 CYCL DEF 7.3 Z+0	
64 LBL 0	
65 LBL 100	SAFE
66 L Z+300 R0 FMAX M3 M91	
67 L X+300 Y-300 R0 FMAX M91	
68 LBL 0	
69 END PGM 1267097 MM	

### 2.3 Programming more than one spatial angle – 1277110

744 650 A4

1:1

Text:		ID number	
		Change No. C000941-05	
		Phase: Nicht-Serie	
		Werkstoff: 3.1645	
		Material:	
		●blanke Flächen/Blank surfaces	
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing	
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715		Allgemeintoleranzen ISO 2768-mH General tolerances ISO 2768-mH	Tolerierung nach ISO 8015 Tolerances as per ISO 8015
		Oberflächenbehandlung: Surface treatment:	
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )			
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created	Responsible	Released
	M-TS		
	11.01.2019		
		Version	Revision
		Sheet	
		Page	
		D1277110-00-A-01	
		1 of 1	
		Document number	




**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill the inclined surface (90°)
- ▶ Mill the inclined surface (110°)
- ▶ Mill the inclined surface (100°)
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

General parameters	Parameters	X	Y	Z
Safety clearance		-	-	+5
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	Ø	T	S	F <sub>1</sub>	DZ	IZ
	20	10	5000	1000	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

**Solution**

0 BEGIN PGM 1277110 MM	
1 BLK FORM 0.1 Z X-75 Y+0 Z-15	
2 BLK FORM 0.2 X+75 Y+50 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 81	PLANE_1
6 CALL LBL 51	MACHINING_1
7 CALL LBL 98	RESET_COORD. TRANS.
8 CALL LBL 82	PLANE_2
9 CALL LBL 51	MACHINING_1
10 CALL LBL 98	RESET_COORD. TRANS.
11 CALL LBL 83	PLANE_3
12 CALL LBL 51	MACHINING_1
13 CALL LBL 98	RESET_COORD. TRANS.
14 CALL LBL 84	PLANE_4
15 CALL LBL 52	MACHINING_2
16 CALL LBL 98	RESET_COORD. TRANS.
17 CALL LBL 85	PLANE_5
18 CALL LBL 52	MACHINING_2
19 CALL LBL 99	RESET
20 M30	
21 LBL 51	MACHINING_1
22 L X+0 Y-20 Z+50 R0 FMAX	
23 L Z+5 R0 FMAX	
24 L Z+0 R0 F AUTO	
25 APPR LT X+0 Y+0 LEN20 RL F AUTO	
26 L Y+50	
27 DEP LT LEN20	
28 L Z+50 R0 FMAX	
29 LBL 0	
30 LBL 52	MACHINING_2
31 L X-20 Y+0 Z+50 R0 FMAX	
32 L Z+5 R0 FMAX	
33 L Z+0 R0 F AUTO	
34 APPR LT X+0 Y+0 LEN20 RL F AUTO	
35 L Y+150	
36 DEP LT LEN20	
37 L Z+50 R0 FMAX	
38 LBL 0	
39 LBL 81	PLANE_1
40 CALL LBL 100	SAFE
41 CYCL DEF 7.0 DATUM SHIFT	


42 CYCL DEF 7.1 X-25	
43 CYCL DEF 7.3 Z-5	
44 PLANE SPATIAL SPA+0 SPB+45 SPC+0 TURN FMAX	
45 LBL 0	
46 LBL 82	PLANE_2
47 CALL LBL 100	SAFE
48 CYCL DEF 7.0 DATUM SHIFT	
49 CYCL DEF 7.1 X+25	
50 CYCL DEF 7.3 Z-5	
51 PLANE SPATIAL SPA+0 SPB+55 SPC+0 TURN FMAX	
52 LBL 0	
53 LBL 83	PLANE_3
54 CALL LBL 100	SAFE
55 CYCL DEF 7.0 DATUM SHIFT	
56 CYCL DEF 7.1 X+25	
57 CYCL DEF 7.2 Y+50	
58 CYCL DEF 7.3 Z-5	
59 PLANE SPATIAL SPA+0 SPB+55 SPC+180 TURN FMAX	
60 LBL 0	
61 LBL 84	PLANE_4
62 CALL LBL 100	SAFE
63 CYCL DEF 7.0 DATUM SHIFT	
64 CYCL DEF 7.1 X-75	
65 CYCL DEF 7.2 Y+36	
66 CYCL DEF 7.3 Z-6	
67 PLANE SPATIAL SPA+0 SPB+50 SPC-90 TURN FMAX	
68 LBL 0	
69 LBL 85	PLANE_5
70 CALL LBL 100	SAFE
71 CYCL DEF 7.0 DATUM SHIFT	
72 CYCL DEF 7.1 X+75	
73 CYCL DEF 7.2 Y+36	
74 CYCL DEF 7.3 Z-6	
75 PLANE SPATIAL SPA+0 SPB+50 SPC+90 TURN FMAX	
76 LBL 0	
77 LBL 98	RESET_COORD. TRANS.
78 PLANE RESET STAY	
79 CYCL DEF 7.0 DATUM SHIFT	
80 CYCL DEF 7.1 X+0	
81 CYCL DEF 7.2 Y+0	
82 CYCL DEF 7.3 Z+0	
83 LBL 0	
84 LBL 99	RESET




85 CALL LBL 100	SAFE
86 PLANE RESET TURN FMAX	
87 CYCL DEF 7.0 DATUM SHIFT	
88 CYCL DEF 7.1 X+0	
89 CYCL DEF 7.2 Y+0	
90 CYCL DEF 7.3 Z+0	
91 LBL 0	
92 LBL 100	SAFE
93 L Z+300 R0 FMAX M3 M91	
94 L X+300 Y-300 R0 FMAX M91	
95 LBL 0	
96 END PGM 1277110 MM	

## 2.4 Programming more than one spatial angle – 1277113

ID number					
Text:	Change No. C000941-05 Phase: Nicht-Serie				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;"> </td> <td style="text-align: center;">Original drawing Scale   Format</td> </tr> <tr> <td style="text-align: center;">RoHS</td> <td style="text-align: center;">1:1   A4</td> </tr> </table>		Original drawing Scale   Format	RoHS	1:1   A4	<b>Platte</b>  <b>plate</b>
	Original drawing Scale   Format				
RoHS	1:1   A4				
Maße in mm / Dimensions in mm Einzelteilzeichnung / Component Drawing					
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715 	Allgemeintoleranzen ISO 2768-mH $\leq 6\text{mm}: \pm 0,2$ General tolerances ISO 2768-mH $\leq 6\text{mm}: \pm 0,2$				
Tolerierung nach ISO 8015 Tolerances as per ISO 8015  Oberflächenbehandlung: Surface treatment:		●blanke Flächen/Blank surfaces Oberflächen nach ISO 1302 Surfaces as per ISO 1302			
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )					
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created   Responsible   Released M-TS     11.01.2019	Version   Revision   Sheet   Page <b>D1277113-00-A-01</b>     1   1 Document number			






**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill islands
  - Rectangular stud
  - Pattern definition
- ▶ Mill the chamfer on the islands
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

Slot milling (roughing)	Parameters	X	Y	Z
Pre-position		0	0	-
Machining direction	Climb milling			
Plunging motion	Reciprocating			
General parameters	Parameters	X	Y	Z
Set-up clearance		-	-	+5
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	Ø	T	S	F <sub>1</sub>	DZ	IZ
	20	10	5000	1000	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

**Solution**

0 BEGIN PGM 1277113 MM	
1 BLK FORM 0.1 Z X+0 Y+0 Z-20	
2 BLK FORM 0.2 X+100 Y+100 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 51	MACHINING_1
6 CALL LBL 99	RESET
7 CALL LBL 81	PLANE_1
8 CALL LBL 52	MACHINING_2
9 CALL LBL 99	RESET
10 CALL LBL 82	PLANE_2
11 CALL LBL 52	MACHINING_2
12 CALL LBL 99	RESET
13 CALL LBL 83	PLANE_3
14 CALL LBL 52	MACHINING_3
15 CALL LBL 99	RESET
16 CALL LBL 84	PLANE_4
17 CALL LBL 52	MACHINING_4
18 CALL LBL 99	RESET
19 M30	
20 LBL 51	MACHINING_1
21 CYCL DEF 256 RECTANGULAR STUD ~	
Q218=+20       ;FIRST SIDE LENGTH ~	
Q424=+40       ;WORKPC. BLANK SIDE 1 ~	
Q219=+15       ;2ND SIDE LENGTH ~	
Q425=+40       ;WORKPC. BLANK SIDE 2 ~	
Q220=+0        ;RADIUS / CHAMFER ~	
Q368=+0        ;ALLOWANCE FOR SIDE ~	
Q224=+0        ;ANGLE OF ROTATION ~	
Q367=+0        ;STUD POSITION ~	
Q207= AUTO     ;FEED RATE MILLING ~	
Q351=+1        ;CLIMB OR UP-CUT ~	
Q201=-10       ;DEPTH ~	
Q202=+5        ;PLUNGING DEPTH ~	
Q206=+250     ;FEED RATE FOR PLNGNG ~	
Q200=+2        ;SET-UP CLEARANCE ~	
Q203=+0        ;SURFACE COORDINATE ~	
Q204=+50       ;2ND SET-UP CLEARANCE ~	
Q370=+1        ;TOOL PATH OVERLAP ~	
Q437=+0        ;APPROACH POSITION ~	
Q215=+1        ;MACHINING OPERATION ~	
Q369=+0        ;ALLOWANCE FOR FLOOR ~	

Q338=+0	;INFEED FOR FINISHING ~	
Q385=+500	;FINISHING FEED RATE	
22	PATTERN DEF ~	
	FRAME1( X+23 Y+25 DX+54 DY+50 NUMX2 NUMY2 ROT+0 ROTX+0 ROTY+0 Z+0 )	
23	L X+0 Y+0 Z+50 R0 FMAX	
24	CYCL CALL PAT FMAX	
25	LBL 0	
26	LBL 52	MACHINING_2
27	CALL LBL 100	SAFE
28	CYCL DEF 7.0 DATUM SHIFT	
29	CYCL DEF 7.1 IX+8	
30	PLANE SPATIAL SPA+0 SPB+45 SPC+0 MOVE	
31	CALL LBL 10	
32	PLANE RESET STAY	
33	CYCL DEF 7.0 DATUM SHIFT	
34	CYCL DEF 7.1 IX-8	
35	CYCL DEF 7.2 IY+5.5	
36	PLANE SPATIAL SPA+0 SPB+45 SPC+90 MOVE	
37	CALL LBL 10	
38	PLANE RESET STAY	
39	CYCL DEF 7.0 DATUM SHIFT	
40	CYCL DEF 7.1 IX-8	
41	CYCL DEF 7.2 IY-5.5	
42	PLANE SPATIAL SPA+0 SPB+45 SPC+180 MOVE	
43	CALL LBL 10	
44	PLANE RESET STAY	
45	CYCL DEF 7.0 DATUM SHIFT	
46	CYCL DEF 7.1 IX+8	
47	CYCL DEF 7.2 IY-5.5	
48	PLANE SPATIAL SPA+0 SPB+45 SPC+270 MOVE	
49	CALL LBL 10	
50	LBL 0	
51	LBL 10	MILLING PATH
52	L X+0 Y-25 Z+50 R0 FMAX	
53	L Z+5 R0 FMAX	
54	L Z+0 R0 F AUTO	
55	L Y+25	
56	LBL 0	
57	LBL 81	PLANE_1
58	CYCL DEF 7.0 DATUM SHIFT	
59	CYCL DEF 7.1 X+23	
60	CYCL DEF 7.2 Y+25	


61 LBL 0	
62 LBL 82	PLANE_2
63 CYCL DEF 7.0 DATUM SHIFT	
64 CYCL DEF 7.1 X+23	
65 CYCL DEF 7.2 Y+75	
66 LBL 0	
67 LBL 83	PLANE_3
68 CYCL DEF 7.0 DATUM SHIFT	
69 CYCL DEF 7.1 X+77	
70 CYCL DEF 7.2 Y+25	
71 LBL 0	
72 LBL 84	PLANE_4
73 CYCL DEF 7.0 DATUM SHIFT	
74 CYCL DEF 7.1 X+77	
75 CYCL DEF 7.2 Y+75	
76 LBL 0	
77 LBL 98	RESET_COORD. TRANS.
78 PLANE RESET STAY	
79 CYCL DEF 7.0 DATUM SHIFT	
80 CYCL DEF 7.1 X+0	
81 CYCL DEF 7.2 Y+0	
82 CYCL DEF 7.3 Z+0	
83 LBL 0	
84 LBL 99	RESET
85 CALL LBL 100	SAFE
86 PLANE RESET TURN FMAX	
87 CYCL DEF 7.0 DATUM SHIFT	
88 CYCL DEF 7.1 X+0	
89 CYCL DEF 7.2 Y+0	
90 CYCL DEF 7.3 Z+0	
91 LBL 0	
92 LBL 100	SAFE
93 L Z+300 R0 FMAX M3 M91	
94 L X+300 Y-300 R0 FMAX M91	
95 LBL 0	
96 END PGM 1277113 MM	




# 3

**Related and further  
topics**

### 3.1 Programming more than one transformation – 1277115





**Working plan**


- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill the inclined surface (10°)
- ▶ Mill the inclined surface (90°)
- ▶ Mill the chamfer
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

Face milling (roughing)	Parameters	X	Y	Z
Milling plan	2, climb milling			
Milling direction	2, parallel to Y axis			
Feed rate for pre-positioning	Maximum feed rate			
Limitation at A+90°	-2, negative minor axis			

General parameters	Parameters	X	Y	Z
Set-up clearance		-	-	+5
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	Ø	T	S	F <sub>1</sub>	DZ	IZ
	20	10	5000	1000	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

**Solution**

0 BEGIN PGM 1277115 MM	
1 BLK FORM 0.1 Z X+0 Y+0 Z-50	
2 BLK FORM 0.2 X+50 Y+50 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 81	PLANE_1
6 CALL LBL 51	MACHINING_1
7 CALL LBL 99	RESET
8 CALL LBL 82	PLANE_2
9 CALL LBL 52	MACHINING_2
10 CALL LBL 99	RESET
11 CALL LBL 83	PLANE_3
12 CALL LBL 53	MACHINING_3
13 CALL LBL 98	RESET_COORD. TRANS.
14 CALL LBL 84	PLANE_4
15 CALL LBL 53	MACHINING_3
16 CALL LBL 98	RESET_COORD. TRANS.
17 CALL LBL 85	PLANE_5
18 CALL LBL 53	MACHINING_3
19 CALL LBL 99	RESET
20 M30	
21 LBL 51	MACHINING_1
22 CYCL DEF 233 FACE MILLING ~	
Q215=+1           ;MACHINING OPERATION ~	
Q389=+2           ;MILLING STRATEGY ~	
Q350=+2           ;MILLING DIRECTION ~	
Q218=+55          ;FIRST SIDE LENGTH ~	
Q219=+50          ;2ND SIDE LENGTH ~	
Q227=+9           ;STARTNG PNT 3RD AXIS ~	
Q386=+0           ;END POINT 3RD AXIS ~	
Q369=+0           ;ALLOWANCE FOR FLOOR ~	
Q202=+5           ;MAX. PLUNGING DEPTH ~	
Q370=+1           ;TOOL PATH OVERLAP ~	
Q207= AUTO        ;FEED RATE MILLING ~	
Q385=+500         ;FINISHING FEED RATE ~	
Q253= MAX         ;F PRE-POSITIONING ~	
Q357=+2           ;CLEARANCE TO SIDE ~	
Q200=+2           ;SET-UP CLEARANCE ~	
Q204=+50          ;2ND SET-UP CLEARANCE ~	
Q347=+0           ;1ST LIMIT ~	
Q348=+0           ;2ND LIMIT ~	
Q349=+0           ;3RD LIMIT ~	


Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
23 L X+0 Y-50 Z+50 R0 FMAX M99		
24 LBL 0		
25 LBL 52		MACHINING_2
26 CYCL DEF 233 FACE MILLING ~		
Q215=+1	;MACHINING OPERATION ~	
Q389=+2	;MILLING STRATEGY ~	
Q350=+2	;MILLING DIRECTION ~	
Q218=+60	;FIRST SIDE LENGTH ~	
Q219=+30	;2ND SIDE LENGTH ~	
Q227=+0	;STARTNG PNT 3RD AXIS ~	
Q386=-10	;END POINT 3RD AXIS ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q202=+5	;MAX. PLUNGING DEPTH ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q385=+500	;FINISHING FEED RATE ~	
Q253= MAX	;F PRE-POSITIONING ~	
Q357=+2	;CLEARANCE TO SIDE ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q347=-2	;1ST LIMIT ~	
Q348=+0	;2ND LIMIT ~	
Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
27 L X+0 Y-30 Z+50 R0 FMAX M99		
28 LBL 0		
29 LBL 53		MACHINING_3
30 L X-25 Y+0 Z+50 R0 FMAX		
31 L Z+5 R0 FMAX		
32 L Z+0 R0 F AUTO		
33 L X+50		
34 L Z+50 R0 FMAX		
35 LBL 0		
36 LBL 81		PLANE_1
37 CALL LBL 100		SAFE
38 CYCL DEF 7.0 DATUM SHIFT		
39 CYCL DEF 7.2 Y+50		
40 PLANE SPATIAL SPA+10 SPB+0 SPC+0 TURN FMAX		


41 LBL 0	
42 LBL 82	PLANE_2
43 CALL LBL 100	SAFE
44 PLANE SPATIAL SPA+90 SPB+0 SPC+0 TURN FMAX	
45 LBL 0	
46 LBL 83	PLANE_3
47 CALL LBL 100	SAFE
48 CYCL DEF 7.0 DATUM SHIFT	
49 CYCL DEF 7.1 Y+50	
50 CYCL DEF 7.2 X+1.9	
51 PLANE SPATIAL SPA+40 SPB+10 SPC-90 TURN FMAX	
52 LBL 0	
53 LBL 84	PLANE_4
54 CALL LBL 100	SAFE
55 CYCL DEF 7.0 DATUM SHIFT	
56 CYCL DEF 7.1 Y+50	
57 PLANE SPATIAL SPA+10 SPB+0 SPC+0 TURN FMAX	
58 CYCL DEF 7.0 DATUM SHIFT	
59 CYCL DEF 7.1 IY-39	
60 PLANE RELATIV SPA+40 TURN FMAX	
61 LBL 0	
62 LBL 85	PLANE_5
63 CALL LBL 100	SAFE
64 CYCL DEF 7.0 DATUM SHIFT	
65 CYCL DEF 7.1 X+48.1	
66 CYCL DEF 7.2 Y+50	
67 PLANE SPATIAL SPA-40 SPB+10 SPC-90 TURN FMAX	
68 LBL 0	
69 LBL 98	RESET_COORD. TRANS.
70 PLANE RESET STAY	
71 CYCL DEF 7.0 DATUM SHIFT	
72 CYCL DEF 7.1 X+0	
73 CYCL DEF 7.2 Y+0	
74 CYCL DEF 7.3 Z+0	
75 LBL 0	
76 LBL 99	RESET
77 CALL LBL 100	SAFE
78 PLANE RESET TURN FMAX	
79 CYCL DEF 7.0 DATUM SHIFT	
80 CYCL DEF 7.1 X+0	
81 CYCL DEF 7.2 Y+0	
82 CYCL DEF 7.3 Z+0	
83 LBL 0	

<b>84 LBL 100</b>	SAFE
<b>85 L Z+300 R0 FMAX M3 M91</b>	
<b>86 L X+300 Y-300 R0 FMAX M91</b>	
<b>87 LBL 0</b>	
<b>88 END PGM 1277115 MM</b>	



### 3.2 Programming more than one transformation – 1277120





Text:		ID number																						
Change No. C000941-05		Phase: Nicht-Serie																						
Werkstoff: 3.1645		Material:																						
<table border="1"> <tr> <th>Original drawing</th> <th>Scale</th> <th>Format</th> </tr> <tr> <td></td> <td>1:1</td> <td>A4</td> </tr> </table>		Original drawing	Scale	Format		1:1	A4	<p><b>Platte</b> <b>plate</b></p>																
Original drawing	Scale	Format																						
	1:1	A4																						
Maße in mm / Dimensions in mm		Einzelteilzeichnung / Component Drawing																						
<p>Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715</p> <p><math>-0.3</math> <math>+0.3</math></p>		<p>Allgemeintoleranzen ISO 2768-mH <math>\leq 6\text{mm}</math>: <math>\pm 0,2</math> General tolerances ISO 2768-mH <math>\leq 6\text{mm}</math>: <math>\pm 0,2</math></p>																						
<p>Tolerierung nach ISO 8015 Tolerances as per ISO 8015</p>		<p>Oberflächen nach ISO 1302 Surfaces as per ISO 1302</p>																						
<p>Oberflächenbehandlung: Surface treatment:</p>		<p>●blanke Flächen/Blank surfaces</p>																						
<p>The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )</p>																								
<p><b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany</p>		<table border="1"> <tr> <th>Created</th> <th>Responsible</th> <th>Released</th> </tr> <tr> <td>M-TS</td> <td></td> <td></td> </tr> <tr> <td>11.01.2019</td> <td></td> <td></td> </tr> </table>	Created	Responsible	Released	M-TS			11.01.2019			<table border="1"> <tr> <th>Version</th> <th>Revision</th> <th>Sheet</th> <th>Page</th> </tr> <tr> <td colspan="3">D1277120-00-A-02</td> <td>1 of 1</td> </tr> <tr> <td colspan="4">Document number</td> </tr> </table>	Version	Revision	Sheet	Page	D1277120-00-A-02			1 of 1	Document number			
Created	Responsible	Released																						
M-TS																								
11.01.2019																								
Version	Revision	Sheet	Page																					
D1277120-00-A-02			1 of 1																					
Document number																								





**Working plan**

- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Face milling
  - **PLANE SPATIAL**
    - Shift datum to tilting edge
- ▶ Mill the other plane surfaces
  - Program section repeat
    - **PLANE RELATIV**
- ▶ Tool call
- ▶ Drill the holes
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

<b>Face milling (roughing)</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Milling plan	2, climb milling			
Milling direction	2, parallel to Y axis			
Feed rate for pre-positioning	Maximum feed rate			
<b>Centering / drilling / thread cutting</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Diameter of counterbore	-5			
Reference for depth	To cylindrical part of the drill (without tool tip)			
Thread pitch	0.7			
<b>General parameters</b>	<b>Parameters</b>	<b>X</b>	<b>Y</b>	<b>Z</b>
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	<b>Ø</b>	<b>T</b>	<b>S</b>	<b>F<sub>1</sub></b>	<b>DZ</b>	<b>IZ</b>
	20	10	1000	5000	-10	5
	10	203	43000	730	-10	5
	3.3	224	3000	800	-10	5
	4	261	1250	-	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining / drilling depth
- IZ) Infeed

**Solution**

0 BEGIN PGM 1277120 MM	
1 BLK FORM CYLINDER Z R40 L30	
2 TOOL CALL 10 Z S5000 F1000	
3 CALL LBL 99	RESET
4 CALL LBL 81	PLANE_1
5 CALL LBL 51	MACHINING_1
6 LBL 10	PROGRAM SECTION REPEAT
7 CALL LBL 82	PLANE_2
8 CALL LBL 51	MACHINING_1
9 CALL LBL 10 REP2	TWO REPETITIONS
10 CALL LBL 99	RESET
11 TOOL CALL 203 Z S1000 F800	
12 CALL LBL 99	RESET
13 CALL LBL 81	PLANE_1
14 CALL LBL 52	MACHINING_2
15 LBL 11	PROGRAM SECTION REPEAT
16 CALL LBL 82	PLANE_2
17 CALL LBL 52	MACHINING_2
18 CALL LBL 11 REP2	TWO REPETITIONS
19 CALL LBL 99	RESET
20 TOOL CALL 224 Z S3000 F800	
21 CALL LBL 99	RESET
22 CALL LBL 81	PLANE_1
23 CALL LBL 53	MACHINING_3
24 LBL 12	PROGRAM SECTION REPEAT
25 CALL LBL 82	PLANE_2
26 CALL LBL 53	MACHINING_3
27 CALL LBL 12 REP2	TWO REPETITIONS
28 CALL LBL 99	RESET
29 TOOL CALL 261 Z S1250	
30 CALL LBL 99	RESET
31 CALL LBL 81	PLANE_1
32 CALL LBL 54	MACHINING_4
33 LBL 13	PROGRAM SECTION REPEAT
34 CALL LBL 82	PLANE_2
35 CALL LBL 54	MACHINING_4
36 CALL LBL 13 REP2	TWO REPETITIONS
37 CALL LBL 99	RESET
38 M30	
39 LBL 51	MACHINING_1
40 CYCL DEF 233 FACE MILLING ~	
Q215=+1 ;MACHINING OPERATION ~	

Q389=+2	;MILLING STRATEGY ~	
Q350=+2	;MILLING DIRECTION ~	
Q218=+40	;FIRST SIDE LENGTH ~	
Q219=+30	;2ND SIDE LENGTH ~	
Q227=+3.5	;STARTNG PNT 3RD AXIS ~	
Q386=+0	;END POINT 3RD AXIS ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q202=+5	;MAX. PLUNGING DEPTH ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q385=+500	;FINISHING FEED RATE ~	
Q253= MAX	;F PRE-POSITIONING ~	
Q357=+2	;CLEARANCE TO SIDE ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q347=+0	;1ST LIMIT ~	
Q348=+0	;2ND LIMIT ~	
Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
41 L X+0 Y-15 Z+50 R0 FMAX M99		
42 LBL 0		
43 LBL 52		MACHINING_2
44 CYCL DEF 240 CENTERING ~		
Q200=+2	;SET-UP CLEARANCE ~	
Q343=+1	;SELECT DIA./DEPTH ~	
Q201=-2	;DEPTH ~	
Q344=-5	;DIAMETER ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q211=+0	;DWELL TIME AT DEPTH ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE	
45 CALL LBL 20		
46 LBL 0		
47 LBL 53		MACHINING_3
48 CYCL DEF 200 DRILLING ~		
Q200=+2	;SET-UP CLEARANCE ~	
Q201=-5	;DEPTH ~	
Q206= AUTO	;FEED RATE FOR PLNGNG ~	
Q202=+5	;PLUNGING DEPTH ~	
Q210=+0	;DWELL TIME AT TOP ~	
Q203=+0	;SURFACE COORDINATE ~	

Q204=+50	;2ND SET-UP CLEARANCE ~	
Q211=+0	;DWELL TIME AT DEPTH ~	
Q395=+1	;DEPTH REFERENCE	
49 CALL LBL 20		
50 LBL 0		
51 LBL 54		MACHINING_4
52 CYCL DEF 207 RIGID TAPPING ~		
Q200=+2	;SET-UP CLEARANCE ~	
Q201=-3	;DEPTH OF THREAD ~	
Q239=+0.7	;THREAD PITCH ~	
Q203=+0	;SURFACE COORDINATE ~	
Q204=+50	;2ND SET-UP CLEARANCE	
53 CALL LBL 20		
54 LBL 0		
55 LBL 20		MACHINING POSITIONS
56 L X+10 Y-12 Z+50 R0 FMAX M99		
57 L X+5 Y+0 Z+50 R0 FMAX M99		
58 L X+10 Y+12 Z+50 R0 FMAX M99		
59 LBL 0		
60 LBL 81		PLANE_1
61 CALL LBL 100		SAFE
62 PLANE SPATIAL SPA+0 SPB+90 SPC+0 TURN FMAX		
63 CYCL DEF 7.0 DATUM SHIFT		
64 CYCL DEF 7.1 Z+36.5		
65 LBL 0		
66 LBL 82		PLANE_2
67 CALL LBL 100		SAFE
68 CYCL DEF 7.0 DATUM SHIFT		
69 CYCL DEF 7.1 Z+0		
70 PLANE RELATIV SPA+90 TURN FMAX		
71 CYCL DEF 7.0 DATUM SHIFT		
72 CYCL DEF 7.1 Z+36.5		
73 LBL 0		
74 LBL 99		RESET
75 CALL LBL 100		SAFE
76 PLANE RESET TURN FMAX		
77 CYCL DEF 7.0 DATUM SHIFT		
78 CYCL DEF 7.1 X+0		
79 CYCL DEF 7.2 Y+0		
80 CYCL DEF 7.3 Z+0		
81 LBL 0		
82 LBL 100		SAFE
83 L Z+300 R0 FMAX M3 M91		

84 L X+300 Y-300 R0 FMAX M91


85 LBL 0

86 END PGM 1277120 MM



### 3.3 Programming more than one transformation – 1277112

Text:		ID number	
		Change No. C000941-05	
		Phase: Nicht-Serie	
		Werkstoff: 3.1645	
		Material:	
		<b>Klotz</b>	
		<b>block</b>	
		Einzelteilzeichnung / Component Drawing	
Maße in mm / Dimensions in mm		●blanke Flächen/Blank surfaces	
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715		Allgemeintoleranzen ISO 2768-mH General tolerances ISO 2768-mH	Tolerierung nach ISO 8015 Tolerances as per ISO 8015
		$\leq 6\text{mm} : \pm 0,2$ $\leq 6\text{mm} : \pm 0,2$	Oberflächen nach ISO 1302 Surfaces as per ISO 1302
Oberflächenbehandlung: Surface treatment:			
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )			
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created	Responsible	Released
	M-TS		
	11.01.2019		
		<b>D1277112-00-A-01</b>	1 of 1
		Document number	



Text:		ID number	
		Change No.:	C000941-05
		Phase:	Nicht-Serie
		Werkstoff:	3.1645
		Material:	
		●blanke Flächen/Blank surfaces	
Maße in mm / Dimensions in mm		Dokumentenart / Document type	
Werkstückkanten nach ISO 13715 Workpiece edges ISO 13715 		Allgometoleranzen ISO 2768-mH ≤6mm: ±0,2 General tolerances ISO 2768-mH ≤6mm: ±0,2	Tolerierung nach ISO 8015 Tolerances as per ISO 8015  Oberflächenbehandlung: Surface treatment:
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design. ( ISO 16016 )			
<b>HEIDENHAIN</b> DR. JOHANNES HEIDENHAIN GmbH 83301 Traunreut, Germany	Created	Responsible	Released
	M-TS		
	11.01.2019		
		Version	Revision
		D1277112-00-A-02	
		Sheet	Page
		1	1
		Document number	

**Working plan**


- ▶ Workpiece blank definition
- ▶ Tool call
- ▶ Mill the slot
- ▶ Pre-rough the inclined surface (45°)
  - **PLANE SPATIAL**
- ▶ Mill the left-hand inclined surface
  - **PLANE SPATIAL**
- ▶ Mill the right-hand inclined surface
- ▶ Finish milling of the inclined surface (45°)
  - **PLANE SPATIAL**
  - **PLANE RELATIV**
- ▶ End the NC program
- ▶ Define subprograms

**Program parameters**

Face milling (roughing)	Parameters	X	Y	Z
Milling plan	2, climb milling			
Milling direction	1, parallel to X axis			
Feed rate for pre-positioning	Maximum feed rate			
Limits	+1, positive principal axis -1, negative principal axis			

General parameters	Parameters	X	Y	Z
Set-up clearance		-	-	+5
Safe position		-	-	+50
Safe tilting position	Relative to the machine datum	+300	-300	+300

**Tool parameters**

	Ø	T	S	F <sub>1</sub>	DZ	IZ
	20	10	5000	1000	-10	5

- Ø) Diameter
- T) Tool number
- S) Speed
- F<sub>1</sub>) Machining feed rate
- DZ) Max. machining depth
- IZ) Infeed

**Solution**

0 BEGIN PGM 1277112 MM	
1 BLK FORM 0.1 Z X-50 Y+0 Z-60	
2 BLK FORM 0.2 X+50 Y+60 Z+0	
3 TOOL CALL 10 Z S5000 F1000	
4 CALL LBL 99	RESET
5 CALL LBL 51	MACHINING_1
6 CALL LBL 81	PLANE_1
7 CALL LBL 52	MACHINING_2
8 CALL LBL 99	RESET
9 CALL LBL 82	PLANE_2
10 CALL LBL 53	MACHINING_3
11 CALL LBL 99	RESET
12 CALL LBL 83	PLANE_3
13 CALL LBL 54	MACHINING_4
14 CALL LBL 99	RESET
15 CALL LBL 81	PLANE_1
16 CALL LBL 55	MACHINING_5
17 CALL LBL 99	RESET
18 CALL LBL 81	PLANE_1
19 CALL LBL 56	MACHINING_6
20 CALL LBL 99	RESET
21 M30	
22 LBL 51	MACHINING_1
23 CYCL DEF 233 FACE MILLING ~	
Q215=+1           ;MACHINING OPERATION ~	
Q389=+2           ;MILLING STRATEGY ~	
Q350=+1           ;MILLING DIRECTION ~	
Q218=-40.5       ;FIRST SIDE LENGTH ~	
Q219=+75         ;2ND SIDE LENGTH ~	
Q227=+0         ;STARTNG PNT 3RD AXIS ~	
Q386=-15         ;END POINT 3RD AXIS ~	
Q369=+0         ;ALLOWANCE FOR FLOOR ~	
Q202=+5         ;MAX. PLUNGING DEPTH ~	
Q370=+1         ;TOOL PATH OVERLAP ~	
Q207= AUTO       ;FEED RATE MILLING ~	
Q385=+500        ;FINISHING FEED RATE ~	
Q253= MAX        ;F PRE-POSITIONING ~	
Q357=+2         ;CLEARANCE TO SIDE ~	
Q200=+2         ;SET-UP CLEARANCE ~	
Q204=+50        ;2ND SET-UP CLEARANCE ~	
Q347=+1         ;1ST LIMIT ~	
Q348=-1         ;2ND LIMIT ~	

Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
24 L X+20.25 Y+0 Z+50 R0 FMAX M99		
25 LBL 0		
26 LBL 52		MACHINING_2
27 CYCL DEF 233 FACE MILLING ~		
Q215=+1	;MACHINING OPERATION ~	
Q389=+2	;MILLING STRATEGY ~	
Q350=+1	;MILLING DIRECTION ~	
Q218=-40.5	;FIRST SIDE LENGTH ~	
Q219=+40	;2ND SIDE LENGTH ~	
Q227=+15	;STARTNG PNT 3RD AXIS ~	
Q386=+0	;END POINT 3RD AXIS ~	
Q369=+0	;ALLOWANCE FOR FLOOR ~	
Q202=+5	;MAX. PLUNGING DEPTH ~	
Q370=+1	;TOOL PATH OVERLAP ~	
Q207= AUTO	;FEED RATE MILLING ~	
Q385=+500	;FINISHING FEED RATE ~	
Q253= MAX	;F PRE-POSITIONING ~	
Q357=+2	;CLEARANCE TO SIDE ~	
Q200=+2	;SET-UP CLEARANCE ~	
Q204=+50	;2ND SET-UP CLEARANCE ~	
Q347=+1	;1ST LIMIT ~	
Q348=-1	;2ND LIMIT ~	
Q349=+0	;3RD LIMIT ~	
Q220=+0	;CORNER RADIUS ~	
Q368=+0	;ALLOWANCE FOR SIDE ~	
Q338=+0	;INFEEED FOR FINISHING ~	
28 L X+20.25 Y-30 Z+50 R0 FMAX M99		
29 LBL 0		
30 LBL 53		MACHINING_3
31 L X+20 Y+20 Z+50 R0 FMAX		
32 L Z+5 R0 FMAX		
33 L Z+0 R0 F AUTO		
34 APPR LT X+0 Y+0 LEN20 RL F AUTO		
35 L Y-30		
36 DEP LT LEN20		
37 L Z+50 R0 FMAX		
38 LBL 0		
39 LBL 54		MACHINING_4
40 L X-20 Y+20 Z+50 R0 FMAX		

41 L Z+5 R0 FMAX	
42 L Z+0 R0 F AUTO	
43 APPR LT X+0 Y-40 LEN20 RL F AUTO	
44 L Y0	
45 DEP LT LEN20	
46 L Z+50 R0 FMAX	
47 LBL 0	
48 LBL 55	MACHINING_5
49 CYCL DEF 7.0 DATUM SHIFT	
50 CYCL DEF 7.1 IX-20.25	
51 PLANE RELATIV SPC-35.2644 STAY	
52 CALL LBL 53	MACHINING_3
53 LBL 0	
54 LBL 56	MACHINING_6
55 CYCL DEF 7.0 DATUM SHIFT	
56 CYCL DEF 7.1 IX+20.25	
57 PLANE RELATIV SPC+35.2644 STAY	
58 CALL LBL 54	MACHINING_4
59 LBL 0	
60 LBL 81	PLANE_1
61 CALL LBL 100	SAFE
62 CYCL DEF 7.0 DATUM SHIFT	
63 CYCL DEF 7.2 Y+15	
64 CYCL DEF 7.3 Z-15	
65 PLANE SPATIAL SPA+45 SPB+0 SPC+0 TURN FMAX	
66 LBL 0	
67 LBL 82	PLANE_2
68 CALL LBL 100	SAFE
69 CYCL DEF 7.0 DATUM SHIFT	
70 CYCL DEF 7.1 X-20.5	
71 CYCL DEF 7.2 Y+15	
72 CYCL DEF 7.3 Z-15	
73 PLANE SPATIAL SPA+35.2644 SPB+0 SPC-45 TURN FMAX	
74 LBL 0	
75 LBL 83	PLANE_3
76 CALL LBL 100	SAFE
77 CYCL DEF 7.0 DATUM SHIFT	
78 CYCL DEF 7.1 X+20.5	
79 CYCL DEF 7.2 Y+15	
80 CYCL DEF 7.3 Z-15	
81 PLANE SPATIAL SPA+35.2644 SPB+0 SPC+45 TURN FMAX	

82 LBL 0	
83 LBL 99	RESET
84 CALL LBL 100	SAFE
85 PLANE RESET TURN FMAX	
86 CYCL DEF 7.0 DATUM SHIFT	
87 CYCL DEF 7.1 X+0	
88 CYCL DEF 7.2 Y+0	
89 CYCL DEF 7.3 Z+0	
90 LBL 0	
91 LBL 100	SAFE
92 L Z+300 R0 FMAX M3 M91	
93 L X+300 Y-300 R0 FMAX M91	
94 LBL 0	
95 END PGM 1277112 MM	